S*ONE HELMET CO.

HOW TO MEASURE YOUR HEAD

- 1 Use a soft tape measure to measure the circumference (around) your head an inch (2.54 cm) above your eyebrows. Keep the tape level from front to back.
- 2 If you don't have a measuring tape, use a piece of string. Then lay the string out on a table and measure the length with a ruler.
- If the helmet is a gift or you cannot measure the head, measure the inside of a current helmet or baseball hat they wear frequently.
- Use the chart to the right to convert inches to centimeters to hat size.



CM	Inches	Hat Size
48	18 7/8	6
49	19 3/8	6 1/8
50	19 5/8	6 1/4
51	20	6 3/8
52	20 1/2	6 1/2
53	20 7/8	6 5/8
54	21 1/4	6 3/4
55	21 5/8	6 7/8
56	22	7
57	22 3/8	7 1/8
58	22 3/4	7 1/4
59	23 1/4	7 3/8
60	23 5/8	7 1/2
61	24	7 5/8
62	24 3/8	7 3/4
63	24 3/4	7 7/8
64	25 1/4	8 1/8
65	25 1/4	8 3/8

S*ONE HELMET COMPANY

s-one.com

